



FIG.3





F 1 G. 4

PC	Network processor	EC
(S1) Dispatch status check command Status check command	Check status signal Status signal=standby (S3) Return "status=standby"	Standby status
(S4) Display power supply status control button with red (S5) Click power supply status control button  Power-on command	Status=standby command  (S6) Confirm that status signal indicates standby status and use power supply control signal to instruct EC to shift to normal operation mode  Shift to normal operation mode	Standby status  Normal operation mode

FIG.5A




FIG.5B